

IN THE DRAWINGS:

The tabs 34 in Figure 2 are shown in their pre-installation state, i.e., prior to being deformed after insertion in the slots 36. This explains why they appear different from the illustrations in Figures 3-5 and 7, which shows the tabs in their deformed state.

Enclosed are replacement sheets containing the following corrections:

Figures 3-5 and 7

The lead lines for reference character 34 have been corrected to point to the tabs 34.

Figure 9

The slots and second opening have been removed from the flange of the upper beam.

IN THE CLAIMS

Please amend the claims in accordance with pages 3 and 4 of this amendment.